

**United States Environmental Protection Agency
Criminal Investigation Division
Investigative Activity Report**

Case Number

0100-0367

Case Title:

Exxon Mobil

Subject of Report:

Interview of Lt. (b)(6), (b)(7) 6/12/06

Copies to:

Reporting Office:

Boston, MA, Area Office

Activity Date:

June 12, 2006

Related Files:

Reporting Official and Date:

(b)(6), (b)(7)(C), SAGT
13-DEC-2006

Approving Official and Date:

(b)(6), (b)(7)(C), SAC
14-DEC-2006
Approved by: (b)(6), (b)(7), SAC

SYNOPSIS

Lt. (b)(6), (b)(7) describes what (b) saw when (b) responded to the Exxon spill on 1-11-06.

DETAILS

On June 12th 2006, S/A (b)(6), and S/A (b)(6), (b) interviewed Lt. (b)(6), (b)(7). (b)(6), (b)(7) is with the U.S. Coast Guard Sector Boston, MA. During the interview, (b)(6), (b)(7) stated in substance the following. Also present at the interview were LCMR (b)(6), MSTC (b)(6), (b), MK2 (b)(6), and MTS3 (b)(6), (b)

(b)(6), (b) arrived at the ExxonMobil containment area around 1:00 pm on January 11, 2006. (b)(6), (b)(7) observed staining on the wooden pier just outside of the containment area. (b)(6), (b)(7) asked an ExxonMobil employee (b) was not sure who it was) about the staining. The employee did not deny seeing the staining, however, the employee responded that it was not from this spill. The employee did not discuss when or which spill that it could have come from.

The vac truck was pumping out the containment area when (b)(6), (b)(7) arrived at ExxonMobil. The containment area was not level, it pitched to the northwest corner. (b)(6), (b)(7) did not see any product flowing out of the side of the containment area. (b) did observe a drip from underneath the containment area.

This document contains neither recommendations nor conclusions of the EPA.
It is the property of the EPA and is loaned to your agency;
it and its contents are not to be distributed outside your agency.